
### The Road Safety Audit Experience



Aaron Johnson – MDOT Superior Region - Ishpeming TSC

# Why have an RSA? "We already know what the problems are here. We already know what we want to do."



### Organizing the RSA

Engineering Enforcement **EMS** Maintenance Local Officials Adjacent property owners

> Schools – Bus Drivers



### Preparing for the RSA

Location for Meeting

Large Van

Existing Plans

Crash History with UD-10s

Background Information

Proposed Project/Plans



### Two Example RSAs


M-26, South Range, Houghton County

M-553, Sands Township, Marquette County




### M-26 South Range





### M-26 South Range





### M-26 South Range






### Curve Visibility - NB



## Curve Visibility



### Signing



Destination Sign - NB


### Short Term Fixes - Signing




### Short Term Fix – Improve signing




### Short Term Fixes - Signing




### Short Term Fixes - Signing



### Geometrics of the Curve



### Geometrics of the Curve




## Long Term Fix – Vertical Curve Flattening



•Eliminate crest vertical curve to provide approach visibility of horizontal curve




### 3. Geometrics of the Curve





## M-553, Marquette County




## M-553, Sands Township Marquette Mountain



### M-553 Curves




### Steep Grades, Lake Effect Snow



### Crashes – 5 years 2007-2011

#### Norway women killed in crash

January 17, 2011 By JOHANNA BOYLE, For The Daily News



MARQUETTE - Two Norway women were killed and two others injured in a two-vehicle accident on M-553 late Saturday morning. The accident caused the road to be closed for about 2 1/2 hours.

According to the Marquette County Sheriff's Office, at about 11:30 a.m. a 1999 Dodge Caravan with three occupants was traveling south on M-553 about a mile and a half south of Marquette Mountain near Glasses Curve when the driver lost control and the vehicle crossed the centerline, hitting a guardrail and a northbound 2005 Chrysler Pacifica.

The Dodge sustained major damage to the passenger side of the vehicle and all three occupants, all of Norway, had to be extricated.

Diane Smith, 49, and her daughter Nicole Smith, 26, the passengers in the right front seat and rear seat, were transported to Marquette General Hospital, where they were pronounced



## 5 Year Crash Listing 2007-2011

REG ION	NUM	C8 MP	PR NUM	PR MP	AREA	TION	TYPE	DIRECTION	OF	OF	DIRECTION	OF	OF	WEA THER	SURFACE	DAY	HOUR	DATE	CRASH ID	П	٩°	PDO			ALCHOL
uperl	52055	14.754	1561008	4.754	Mid-block	straight,	FXOBJ	VEHICLE1 Unknown	VEHICLE1 Rear	VEHICLE1 Going	VEHICLE2 Unknown	VEHICLE2 Uncoded	VEHICLE2 Uncoded	Snow	ITION	Mon	1000	12/14/2009	749431		00	Υ	INJ 0	FATAL 0	No
uperl	EDDEE	14 754	1551000	14.754	Mid-block	unrel	FXOBJ	South	Corner; Other	Straight Going	Unknown	Errors Uncoded	Error	/ Snow	Snowy	Tue	0650	10/13/2009	740740		1		0	0	No
upen	32033	14.754	1301000	14.754	MIG-DIOCE	unrel	FAUDJ	South	Unknown	Straight	CHRIOWII	Errors	Error	J /	SHOWY	Tue	ucou	10/13/2009	142142	90	ľ	_	Ů	u	NO
uperl	52055	14.754	1561008	4.754	Mid-block	straight, unrei	FXOBJ	North	Front Comer; D	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	Slushy	Thu	0920	12/01/2011	820392	10	0 0	Υ	0	0	No
uperl	52055	14.754	1561008	4.754	Mid-block	curved road,	OTURN	North	Side; Driver Si	Uncoded Error	Unknown	Uncoded Errors	Uncoded Error	Clear	lcy	Wed	0630	11/18/2009	746134	9 0	00	Υ	0	0	No
uperl	52055	14.754	1561008	4.754	Mid-block	curved road.	AN-ST	North	Multiple Areas	Going Straight	East	Front Center	Going Straight	Snow /	Slushy	Thu	1005	12/29/2011	823321	2 0	10	N	1	1	No
uperl	52055	14.754	1561008	14.754	Mid-block	straight, unrei	RE-ST	South	Rear Center	Parked	South	Front Center	Going Straight	Cloudy	Dry	Fri	2150	02/16/2007	660047	4 1	0 0	N	1	0	No
uperl	52055	14.754	1561008	4.754	Mid-block	curved road.	PKD-V	North	Multiple Areas	Going Straight	West	Front Corner: P	In prior crash	Clear	icy	Wed	0635	11/18/2009	746229	2 0	10	N	1	0	No
uperl	52055	14.756	1561008	4.756	Mid-block	straight, unrei	3C-SNG	South	Front Center	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow	Slushy	Wed	1550	11/09/2011	820322	0 0	00	Υ	0	0	No
uperl	52055	14.811	1561008	14.811	Mid-block	straight, unrei	BIKE	South	Side; Passenge	Going Straight	Unknown	Uncoded Errors	Pedestriar In r	Clear	Dry	Tue	1820	06/22/2010	764573	B 1	0 0	N	1	0	No
uperl	52055	14.811	1561008	14.811	Mid-block	curved road.	FXOBJ	North	Front Comer; D	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Clear	Dry	Tue	2110	08/31/2010	769829	3 1	0 0	N	1	0	Yes
uperl	52055	14.954	1561008	14.954	Mid-block	curved road,	FXOBJ	South	Rear Corner;	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	Slushy	Thu	1240	04/12/2007	664972	40	00	Υ	0	0	No
uperl	52055	15.254	1561008	15.254	Mid-block	curved road,	FXOBJ	Unknown	Front Corner; P	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	lcy	Tue	0645	01/18/2011	786890	3 0	00	Υ	0	0	No
uperl	52055	15.254	1561008	15.254	Mid-block	curved road,	HD-ON	North	Front Center	Going Straight	South	Front Center	Going Straight	Snow /	Slushy	Tue	0805	10/13/2009	744390	5 1	1 0	N	2	0	No
uperl	52055	15.254	1561008	15.254	Mid-block	curved road,	HD-ON	South	Side; Passenge	Going Straight	North	Front Center	Going Straight	Snow /	Snowy	Sat	1132	01/15/2011	792997	0 1	1 0	N	2	2	No
uperi	52055	15.256	1561008	15.256	Mid-block	curved road,	SS-OP	South	Rear Corner;	Uncoded Error	North	Side; Passenger	Uncoded Error	Snow /	Snowy	Tue	0745	01/30/2007	657975	0 0	00	Υ	0	0	No
uperl	52055	15.256	1561008	15.256	Mid-block	curved road,	FXOBJ	South	Front Center	Unknown	Unknown	Uncoded Errors	Uncoded Error	Clear	Snowy	FrI	1050	02/09/2007	659396	60	0 1	N	1	0	No
uperl	52055	15.256	1561008	15.256	Mid-block	curved road,	FXOBJ	South	Front Corner; P	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	lcy	Thu	0520	02/15/2007	660063	0 0	0 0	Υ	0	0	No
uperl	52055	15.336	1561008	15.336	Mid-block	curved road,	3C-SNG	North	Rear Corner;	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Rain	Wet	Thu	1215	10/18/2007	680372	9 0	00	Υ	0	0	No
uperl	52055	15.454	1561008	15.454	Mid-block	curved road,	FXOBJ	South	Front Center	Slowing Stopped	Unknown	Uncoded Errors	Uncoded Error	Snow /	icy	Mon	1810	12/14/2009	750004	5 0	2 0	N	2	0	No
uperi	52055	15.518	1561008	15.518	Mid-block	curved road,	FXOBJ	North	Front Corner; P	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	icy	Mon	0920	02/02/2009	724824	5 0	0 0	Υ	0	0	No
uperi	52055	15.654	1561008	15.654	Mid-block	curved road,	SS-SM	South	Front Corner; P	Slowing Stopped	South	Rear Corner; Dr	Avoiding the veh	Cloudy	icy	Tue	1550	01/05/2010	752014	5 0	0 0	Υ	0	0	No
uperi	52055	15.654	1561008	15.654	Mid-block	curved road,	FXOBJ	South	Front Corner; P	Avoiding the veh	Unknown	Uncoded Errors	Uncoded Error	Cloudy	icy	Tue	1550	01/05/2010	752006	10	0 0	Υ	0	0	No
uperl	52055	15.654	1561008	15.654	Mid-block	curved road,	RE-ST	South	Rear Corner;	Stopped on Road	South	Front Corner; P	Going Straight	Cloudy	icy	Tue	1550	01/05/2010	752006	2 0	0 0	Υ	0	0	No
uperl	52055	15.654	1561008	15.654	Mid-block	straight, unrei	FXOBJ	South	Front Comer, D	Going Straight	Unknown	Uncoded Errors	Uncoded Error	Snow /	lcy	Tue	1525	01/05/2010	752006	00	0 0	Υ	0	0	No

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_
Occasional	High	High	E






SUGGESTION: Improve horizontal and vertical curve geometrics to meet 60 MPH design speed, (50 MPH currently). Includes superelevation improvements.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_				
Occasional	High	High	E				
ODCEDVATION D:							







SUGGESTION: Increase sign sizes and reduce sign location offset. Upgrade sign sheeting. Upgrade signs to meet current MMUTCD. Add reflective sheeting to sign posts. Add chevrons and target arrows to all curve sections. Add advisory speeds to advance curve warning signs. Add object marker signs to end of guardrail sections.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_
Occasional	High	High	E



SUGGESTION: Remove and consolidate the passing zones. Remove all corresponding signs and repaint pavement markings to reflect the change.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_
Occasional	High	High	



SUGGESTION: Place a special detail sign at the beginning of the segment in each direction to indicate hill terrain and curves ahead.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_
Occasional	High	High	E .

OBSERVATION: Crashes are occurring at the end of the taper section in the horizontal curve, (near the driveways to the north).






SUGGESTION: Short Term - Update taper warning signs to reflect MMUTCD. Long Term - Extend the truck climbing lane to the tangent portion of M-553, (~3500' further).

Occasional	Medium	Moderate	D
EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	

OBSERVATION: Northern curve near Marquette Mtn. is limited to any geometric realignment.



SUGGESTION: Add a high friction surface to roadway. Clear trees and other fixed objects in clear zone. Cut down and move the backslopes further from the roadway.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	_
Rare	High	Moderate	ע

OBSERVATION: Possible foreslopes may requiring shielding.



SUGGESTION: Extend guardrail to shield foreslopes. Extend approach terminal.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	<b>D</b>
Rare	High	High	D

OBSERVATION: Potential bicycle conflicts.





SUGGESTION: Increase shoulder width to uniform standard. Add rumble strips in shoulder where missing. Potentially add bicycle share the road signs.

EXPECTED FREQUENCY	EXPECTED SEVERITY	RISK RATING	
Rare	Medium	Low	

OBSERVATION: Pedestrian conflicts near Marquette Mtn. at the pedestrian roadway crossing.





SUGGESTION: Update pedestrian crossing sequence; Including high visibility pedestrian pavement markings, pedestrian signing upgrades, and adding diagonal target arrows at crossing.

### Summary

### Low Cost:

Update signing, pavement markings, guardrail, rumble strips, and consolidating passing zones.

### Moderate Cost:

 Shoulder widening, high friction surface, horizontal sight distance improvements (trees/backslopes).

### High Cost:

Realign horizontal curves, improve vertical curves, improve superelevation, and extend truck lane.

### Questions?

